



## ZIPPER SLIDER NOTICE



### YKK ZIPPER SLIDER INFO

Since 2020, we have seen several cases of YKK locking sliders that do not function normally. Usually this results in the zipper slider moving on the zipper during flight or traveling when it should not.

The following information and videos explain the root cause of this problem, and how to fix it.

#### Background Info:

Watch this video for a full explanation: <https://vimeo.com/flysquirrel/ykkzipperslider>

The YKK 10C zipper is the best zipper we know of for the job. However, even the best stuff sometimes isn't perfect. Some YKK sliders have been letting us down, and we now have a "patch" to fix this issue. The replacement slider lanyards work well, and are very secure.

If your sliders aren't staying put, [email us](mailto:fly@squirrel.ws) (fly@squirrel.ws) and we will ship you the replacement lanyard kit.

#### Replacement Lanyard Installation:

Watch this video for instructions on how to install the replacement lanyards:

<https://vimeo.com/flysquirrel/zippersliderlanyard>

#### Quick Rubber Band Patch:

Want a temporary quick fix, right now? This quick rubber band patch will get you through the next days / weeks, if you are patient enough to thread the needle:

<https://vimeo.com/flysquirrel/zippersliderpatch>